




Notification regarding Change in External Appearance of the Auxiliary Terminal of New SC and NEO SC Series Magnetic Contactors and Starters

We would like to thank you for your continued patronage of Fuji products.

We will be changing some products as described below.

Please review the following information and take appropriate actions.

Please also inform all related sections of your company of these changes.

Product name	Magnetic contactors, magnetic starters, auxiliary contact blocks
Series name	New SC Series, NEO SC Series, SC-E Series
Types	<p>1) Magnetic contactors and starters: SC(SW)-N4 to SC(SW)-N14, SC-N16, SC(SW)-5-1(2A2B), SC-E02RM to SC-E4RM</p> <p>2) Auxiliary contact blocks (front mounting): SZ-A□□</p> <p>3) Auxiliary contact blocks (side mounting): SZ-AS1, SZ-AS2, SZ-AS3N</p> <p>Applicable to all products that begin with the product types indicated in 1) to 3) above (including applied products such as reversible, high-capacity auxiliary contacts).</p>
Changed parts	Auxiliary terminal (Only the auxiliary terminal will be changed for magnetic contactors and magnetic starters.)
Details of the change	<p>The color of the terminal for tightening the terminal screws will be changed (Will become a more yellowish color).</p> <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;">  <p>[Conventional product] [Changed product]</p> <p>Fig. 1: Description of changes Auxiliary contact block SZ-A40 example (The bottom row shows the terminal screws removed)</p> </div> <div style="text-align: center;">  <p>Fig. 2: SC-N4 to SC-N16 changes (SC-N5 example)</p> </div> <div style="text-align: center;">  <p>Fig. 3: SZ-AS□ changes (SZ-AS1 example)</p> </div> </div>
Reason for change	To facilitate material procurement
Date of the production change	Scheduled for products to be produced from August 2019
Attachment	None
Notes concerning the change	With regard to auxiliary contact blocks: SZ-AS1 and SZ-AS2, the change coincides with Rep. No. B18067 [Notification regarding Change in the Side Nameplate of Some New SC/SK Series Auxiliary Relays and Auxiliary Contact Blocks] published in February 2019.