

To Our Customers

Ref: FESN-2207 End of Sep. 2022 Fuji Electric Co., Ltd.

Fuji Electric Ship Exhaust Gas Cleaning System (EGCS) <u>Undisplayed PAH Value</u>

We would like to express our deepest appreciation to you for your continued support for our ship exhaust gas cleaning systems (EGCS).

We received the a few report from vessels that PAH figures are not displayed during operation. For exact solution, please contact us when the following situations have been occurred.

[Situations]

The value is not displayed in TrioBOX3, and the value of Control Panel and Operation Panel indicates "0".


[Cause]


By combining the software version on TriBOX3 with the type of PAH sensor

[Inquiry Address] egcs@fujielectric.com

TriBOX







Yours sincerely,