

To All Customers

Rep No. B19050
November 11, 2019
Fuji Electric FA Components
& Systems Co., Ltd.








Notification regarding Change to Internal Accessory Terminal Block Bracket Mounting Position
of BX Series Solid-State Molded Case Circuit Breaker

We would like to thank you for your continued patronage of Fuji products.
We will be changing some products as described below.
Please review the following information and take appropriate actions.
Please also inform all related sections of your company of these changes.

Product name	Molded Case Circuit Breaker/Earth Leakage Circuit Breaker
Series name	Accessory terminal block for BX Series solid-state molded case circuit breakers
Types	BX800RAE, BX1000RAE, BX1250RAE, BX1600RAE, BX800HAE, BX1000HAE, BX1250HAE, BX1600HAE
Changed parts	Terminal block bracket mounting position for internal accessories
Details of the change	We are changing the terminal block bracket mounting position for internal accessories from between the case and cover to the top surface of the cover.
Reason for change	To improve productivity.
Date of production change	Scheduled for products to be produced from March 2020
Attachments	"Change to Internal Accessory Terminal Block Bracket Mounting Position"
Notes concerning the changes	This change will not affect product performance.

[Details of the change]

The position of the internal accessory terminal block mounting bracket will be changed from between the case and cover to the upper surface of the cover.

Current product	Changed product
<p>Front</p> 	<p>Front</p> 
<p>Side</p> 	<p>Side</p> 
<p>Side  magnified</p> 	<p>Side  magnified</p> 