

To All Customers

Rep No. C19004
November 11, 2019
Fuji Electric FA Components
& Systems Co., Ltd.

Announcement regarding Discontinuation of Auxiliary Parts for Old-Type SB-2N DC Magnetic Contactors

We would like to thank you for your continued patronage of Fuji products.

We are writing to inform you of the discontinuation of auxiliary parts for applicable products discontinued in March 2014 in accordance with Rep. No. C13007, issued in October 2013.

Although we announced that auxiliary parts would be available for 7 years following the discontinuation, the production of these parts has become difficult.

Therefore, we sincerely apologize for the inconvenience, but will be discontinuing the supply of these parts as of March 2019. Please also inform all related sections of your company of these changes.

1. Types subject to discontinuation

Contact kits and coils for SB-2N and SB-2NB

- Moving contacts (SC moving contact SB-2N□□)
- Fixed contacts (SC fixed contact SB-2N□□)
- Coil (coil unit □□□V)

2. Timing of supply discontinuation

Immediately.

(Supply of auxiliary parts has become difficult for the following reasons. Therefore, please use alternative parts.)

3. Reason for supply discontinuation

We will be discontinuing the supply due to production equipment failure and low demand for the parts.

4. Others

- For alternative types, please refer to the Production Discontinuation Report (Rep. No. C13007).
- As described in Rep. No. C13007, the products subject to discontinuation at the end of March 2014 are as follows:

Magnetic contactors: SB-2N, SB-2N/SE types

SB-2NB, SB-2NB/SE types

(Includes all applicable parts such as mechanical latches and main nonpolar contact types)

Optional parts: (Auxiliary contact block) SZ-1N/AL2, AR2 (bifurcated type)

SZ-1N/CL1, CR1 (single type)

(Live-section protective cover) SZ-1N/T